

11/10/2017

Drainfield Stilling Tank & Dropbox Inspection Results

Drainfield Designation	Type	Stilling Tank	Effluent Depth	Sludge Depth	No. of Dropboxes	Used Dropboxes	Percent Used	Comments
DF-1	Field	Yes	3'-0"	3"	13	5	38%	Partially covered with brush
DF-2	Field	Yes	3'-0"	1"	6	5	83%	Small tree on dropbox, brush, wood chuck hole
DF-3	Field	Yes	3'-0"	1"	9	4	44%	Partially covered with brush
DF-4	Field	Yes	3'-0"	1"	6	6	100%	All dropboxes being used
DF-5A	Field	Yes	3'-0"	1"	8	5	63%	Partially covered with brush
DF-5B	Field	No	N/A	N/A	4	1	25%	
DF-6	Field	No	N/A	N/A	6	3	50%	ATV trail on drainfield
DF-7	Field	Yes	3'-0"	1"	9	3	33%	
DF-8	Field	Yes	3'-0"	3"	11	3	27%	
DF-9	Field	Yes	3'-0"	2"	6	4	67%	
DF-10	Field	Yes	3'-0"	4"	9	4	44%	Some brush and broken inspection pipe.
DF-11	Field	Yes	3'-0"	3"	10	4	40%	Partially covered with brush
DF-12	Field	Yes	3'-0"	2"	6	4	67%	
M-1A	Mound	N/A	N/A	N/A	N/A	N/A	N/A	No stilling tanks or dropboxes w/mound system
M-1B	Mound	N/A	N/A	N/A	N/A	N/A	N/A	No stilling tanks or dropboxes w/mound system
M-1C	Mound	N/A	N/A	N/A	N/A	N/A	N/A	No stilling tanks or dropboxes w/mound system
M-2A	Mound	N/A	N/A	N/A	N/A	N/A	N/A	No stilling tanks or dropboxes w/mound system
M-2B	Mound	N/A	N/A	N/A	N/A	N/A	N/A	No stilling tanks or dropboxes w/mound system
M-3A	Mound	N/A	N/A	N/A	N/A	N/A	N/A	No stilling tanks or dropboxes w/mound system
M-3B	Mound	N/A	N/A	N/A	N/A	N/A	N/A	No stilling tanks or dropboxes w/mound system
M-4A	Mound	N/A	N/A	N/A	N/A	N/A	N/A	No stilling tanks or dropboxes w/mound system
M-4B	Mound	N/A	N/A	N/A	N/A	N/A	N/A	No stilling tanks or dropboxes w/mound system

Drainfield Stilling Tank & Dropbox Inspection Notes:

1. Stilling tank effluent depth and sludge depth checked by Hassle Free Septic Service on 11/10/17. Because of the minimal amount of sludge found, no tanks will need to be pumped.
2. Drop box usage checked by Hassle Free Septic, Tom Davis and Garry Weisinger of TTHA at the same time the tanks were checked. This report was done by Garry Weisinger.
3. All brush on septic fields will need to be removed next spring.
4. All of the dropboxes have been used in DF-4 which means this drain field might be running near full capacity. We will need to watch this drain field to see if it continues to operate properly.
5. I needed to revise the drainfield map based on our inspections and have included the revised map with this document.